

CERTIFICATE OF COMPLIANCE

Certificate Number 20171106-R38772
Report Reference R38772-20171106
Issue Date 2017-NOVEMBER-06

Issued to: ACTIVE VENTILATION PRODUCTS INC
311 1St St
Newburgh NY 12550-4857

**This is to certify that
representative samples of**

Products for Use in Windstorm-Rated Assemblies;
Windstorm-Rated Assemblies

Roof Vents – Aura Vent Series: Models AV-04-C02, AV-04-C04, AV-04-C06, AV-04-C08, AV-04-C12, AV-06-C02, AV-06-C04, AV-06-C06, AV-06-C08, AV-06-C10, AV-08-C02, AV-08-C04, AV-08-C06, AV-08-C08, AV-08-C12, AV-10-C02, AV-10-C04, AV-10-C06, AV-10-C08, AV-10-C12, AV-12-C02, AV-12-C04, AV-12-C06, AV-12-C08, AV-12-C12, AV-14-C02, AV-14-C04, AV-14-C06, AV-14-C08, AV-14-C12, AV-16-C02, AV-16-C04, AV-16-C06, AV-16-C08, AV-16-C12, AV-18-C02, AV-18-C04, AV-18-C06, AV-18-C08, AV-18-C12, AV-20-C02, AV-20-C04, AV-20-C06, AV-20-C08, AV-20-C12, AV-24-C02, AV-24-C04, AV-24-C06, AV-24-C08, AV-24-C12.

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety:

- TAS 202, Impact and Non Impact Resistant Building Envelope Components Using Uniform Static Air Pressure.
- ASTM E330, Structural Performance of Exterior Windows, Doors, Skylights and Curtain Walls by Uniform Static Air Pressure Difference.
- California Building Code, Chapter 7A, Materials and Construction Methods for Exterior Wildfire Exposure; Section 706A.2, Requirements.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>




CERTIFICATE OF COMPLIANCE

Certificate Number 20171106-R38772
Report Reference R38772-20171106
Issue Date 2017-NOVEMBER-06

Additional Information: See the UL Online Certifications Directory at www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

